HISTORIG AMERIGAN ENGINEERING REGORD

HAER MASS. 9-LOW, 22-A-

Index to Photographs

Massachusetts Mills, Cloth Room/Section 15 95 Bridge Street Lowell Locks and Canal Historic District Lowell Middlesex Massachusetts HAER No. MA-89-A

- NOTE: Photographs MA-89-A-1 through MA-89-A-3 and MA-89-A-5 through MA-89-A-10 were taken by Ernest Gould with Christopher Closs, April 1989
 - Photographs MA-89-A-4 and MA-89-A-11 through MA-89-A-18 were taken by Ernest Gould with Christopher Closs, June 1989
- MA-89-A-1 VIEW OF SOUTHWEST ELEVATION SHOWING LOADING DOGK AND CANTED CORNER WITH OFFICE ENTRANCE, LOOKING NORTHEAST. EASTERN CANAL IS IN FOREGROUND
- MA-89-A-2 VIEW OF NORTHWEST ELEVATION SHOWING FORMER INTERIOR PARTY WALL FROM STOREHOUSE "B" AT LEFT; CANTED GORNER (WEST ELEVATION) AT RIGHT, LOOKING SOUTHEAST. EASTERN CANAL IS IN FOREGROUND.
- MA-89-A-3 VIEW OF NORTHEAST ELEVATION AND 1906-1010 ONE-STORY SHED ADDITION AT LEFT; NORTHWEST ELEVATION AND PARKING AREA AT RIGHT; PARKING AREA WAS SITE OF FORMER STOREHOUSE "A" AND "B"; LANE AT LEFT IS NORTH DRIVEWAY, BUILT GA. 1935
- MA-89-A-4 VIEW SHOWING NORTHEAST ELEVATION WITH STEEL SASH AND STUGGO WALL FINISH, LOOKING SOUTH; 1906-1910 ONE-STORY SHED ADDITION WITH ROOF MONITOR IS IN FOREGROUND LEFT
- MA-89-A-5 VIEW OF SOUTHEAST AND NORTHEAST ELEVATIONS, SHOWING BRIDGE TO NAPPING BUILDING AT LEFT AND STEEL I-BEAM HOIST ON ROOF WITH PARAPET, LOOKING WEST
- MA-89-A-6 VIEW OF SOUTHEAST ELEVATION, SHOWING BRIDGE TO NAPPING BUILDING AT LEFT, OVERHEAD; AND ALTERATIONS OF FENESTRATION FOR TWO FREICHT DELIVERY DOORS, LOOKING NORTH. DOUBLE DOOR AT LEFT SERVES SOUTH STAIR TOWER
- MA-89-A-7 VIEW SHOWING EAST ELEVATION OF OVERHEAD BRIDGE CONNECTING NAPPING BUILDING (LEFT) WITH GLOTH ROOM (RIGHT), LOOKING WEST

Massachusetts Mills, Cloth Room/Section 15 HAER No. MA-89-A Index to Photographs (Page 2)

- MA-89-A-8 VIEW SHOWING UNDERSIDE OF BRIDGE BETWEEN NAPPING BUILDING AND CLOTH ROOM, INCLUDING STEEL LEGS, STRUCTURAL CONFIGURATION OF CONCRETE BRIDGE FLOOR, AND CANTED CONNECTION WITH THIRD STORY OF CLOTH ROOM, LOOKING NORTH
- MA-89-A-9 VIEW OF BASEMENT, NORTH SECTION, SHOWING TYPICAL PIER, FOOTINGS, AND STRUCTURAL MEMBERS FOR FIRST FLOOR ABOVE, LOOKING WEST
- MA-89-A-10 VIEW OF FIRST FLOOR, NORTH SIDE OR INSIDE OF VESTICIAL WALL OF ORICINAL 1839 COTTON HOUSE, LOOKING WEST. ORIGINAL WINDOW OPENINGS ARE BRICKED IN
- MA-89-A-11 INTERIOR VIEW OF 1906-1910 ONE-STORY SHED ADDITION, FIRST FLOOR, SHOWING ROOF MONITOR, LOOKING NORTHWEST
- MA-89-12 VIEW ALONG SOUTHWEST SIDE OF SECOND FLOOR, SHOWING TYPICAL STRUCTURAL CONFICURATION AND CONTEMPORARY PARTITIONING FOR OFFICES, LOOKING SOUTH
- MA-89-A-13 VIEW OF CENTER OF NORTH SECTION, SECOND FLOOR, SHOWING TYPICAL SPACE AND STRUCTURAL CONFICURATION, LOOKING EAST
- MA-89-A-14 DETAIL VIEW OF NORTH STAIR TOWER, NORTH CORNER, SECOND FLOOR
- MA-89-A-15 VIEW OF SOUTH STAIR TOWER ENCLOSURE, SOUTH CORNER, SECOND FLOOR
- MA-89-A-16 DETAIL VIEW OF SOUTH STAIR TOWER, SOUTH CORNER, SECOND FLOOR
- MA-89-A-17 DETAIL VIEW OF SAWTOOTH MONITOR ROOF, CENTER OF NORTH SECTION, THIRD FLOOR, LOOKING NORTHWEST
- MA-89-A-18 DETAIL VIEW SHOWING SAWTOOTH MONITOR ROOF AND TYPICAL STRUCTURAL CONFICURATION OF TOP STORY, NORTH SECTION, THIRD FLOOR, LOOKING WEST INTO SOUTH SECTION

MASSACHUSETTS MILLS, CLOTH ROOM/SECTION 15 HAER NO. MA-89-A (Page 3) KEY TO PHOTOGRAPHS KEY TO PHOTOS (NOS. 1-18) Exterior Elevations First Floor Basement Second Floor Third Floor